

**Mätning och bedömning av exponering för
inkoherent optisk strålning –
Del 2: VIS- och IR-strålning från artificiella källor
på arbetsplatser**

**Measurement and assessment of personal
exposures to incoherent optical radiation –
Part 2: Visible and infrared radiation emitted by
artificial sources in the workplace**

Europastandarden EN 14255-2:2005 gäller som svensk standard. Detta dokument innehåller den officiella engelska versionen av EN 14255-2:2005.

The European Standard EN 14255-2:2005 has the status of a Swedish Standard. This document contains the official English version of EN 14255-2:2005.

Uppllysningar om **sakinnehållet** i standarden lämnas av SIS, Swedish Standards Institute, telefon 08 - 555 520 00.

Standarder kan beställas hos SIS Förlag AB som även lämnar **allmänna upplysningar** om svensk och utländsk standard.

Postadress: SIS Förlag AB, 118 80 STOCKHOLM
Telefon: 08 - 555 523 10. *Telefax:* 08 - 555 523 11
E-post: sis.sales@sis.se. *Internet:* www.sis.se

EUROPEAN STANDARD
NORME EUROPÉENNE
EUROPÄISCHE NORM

EN 14255-2

December 2005

ICS 13.280

English Version

Measurement and assessment of personal exposures to incoherent optical radiation - Part 2: Visible and infrared radiation emitted by artificial sources in the workplace

Mesure et évaluation de l'exposition des personnes aux rayonnements optiques incohérents - Partie 2 : Rayonnements visibles et infrarouges émis par des sources artificielles sur les lieux de travail

Messung und Beurteilung von personenbezogenen Expositionen gegenüber inkohärenter optischer Strahlung - Teil 2: Sichtbare und infrarote Strahlung künstlicher Quellen am Arbeitsplatz

This European Standard was approved by CEN on 4 November 2005.

CEN members are bound to comply with the CEN/CENELEC Internal Regulations which stipulate the conditions for giving this European Standard the status of a national standard without any alteration. Up-to-date lists and bibliographical references concerning such national standards may be obtained on application to the Central Secretariat or to any CEN member.

This European Standard exists in three official versions (English, French, German). A version in any other language made by translation under the responsibility of a CEN member into its own language and notified to the Central Secretariat has the same status as the official versions.

CEN members are the national standards bodies of Austria, Belgium, Cyprus, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Slovakia, Slovenia, Spain, Sweden, Switzerland and United Kingdom.



EUROPEAN COMMITTEE FOR STANDARDIZATION
COMITÉ EUROPÉEN DE NORMALISATION
EUROPÄISCHES KOMITEE FÜR NORMUNG

Management Centre: rue de Stassart, 36 B-1050 Brussels

Contents

	Page
Foreword	4
Introduction.....	5
1 Scope	7
2 Normative references	7
3 Terms and definitions	8
3.1 Quantities, symbols and units	8
3.2 Definitions and relationships between quantities	9
4 General procedure	11
5 Preliminary review	12
6 Work task analysis.....	12
7 Measurement of the exposure	13
7.1 Planning.....	13
7.2 Quantities to be determined.....	14
7.3 Selection of method.....	14
7.4 Requirements for the measurement methods	17
7.5 Implementation.....	19
7.6 Expression of results.....	20
8 Assessment of the exposure	20
8.1 Comparison	20
8.2 Statement.....	20
8.3 Additional information	20
9 Decision about protective measures.....	21
10 Repetition of measurement and assessment	21
11 Report	21
11.1 Short Report.....	21
11.2 Full Report.....	22
Annex A (informative) Flow chart of procedure	23
Annex B (informative) Tables (examples) for work task analysis.....	24
Annex C (informative) Commonly used radiation measurement devices	26
Annex D (informative) Examples of protective measures	28
Annex E (informative) Examples of methods for the determination of the quantities L_r , L_b , G_b , H_b , E_b , E , H and the assessment of associated hazards	29
Table 1 – Quantities, symbols and units	8
Table 2 – Suitable methods for the measurement of the quantities L_r , G_b , H_b , E_b , E and H in dependence of the measurement aim and the exposure conditions (see Annex E).....	16
Table B.1 – Basic information.....	24
Table B.2 – Detailed information concerning activities at a single location	25
Table E.1 – Survey of suitable measurement methods.....	30
Table E.2 – Advantages and disadvantages of method A	31
Table E.3 – Advantages and disadvantages of method B	32

Table E.4 – Advantages and disadvantages of method C	33
Table E.5 – Advantages and disadvantages of method D	34
Table E.6 – Advantages and disadvantages of method E	35
Table E.7 – Advantages and disadvantages of method F.....	36
Table E.8 – Advantages and disadvantages of method G	37
Table E.9 – Advantages and disadvantages of method H	38
Table E.10 – Advantages and disadvantages of method I.....	40
Table E.11 – Advantages and disadvantages of method J.....	41
Table E.12 – Advantages and disadvantages of method K	42
Table E.13 – Advantages and disadvantages of method L.....	42
Table E.14 – Advantages and disadvantages of method M.....	43
Table E.15 – Advantages and disadvantages of method N	44
Table E.16 – Advantages and disadvantages of method O	45
Table E.17 – Advantages and disadvantages of method P.....	46
Table E.18 – Advantages and disadvantages of method Q.....	46
Table E.19 – Advantages and disadvantages of method R	47
Table E.20 – Advantages and disadvantages of method S.....	48
Table E.21 – Advantages and disadvantages of method T.....	48
Table E.22 – Advantages and disadvantages of method U	49
Table E.23 – Advantages and disadvantages of method V.....	50
Table E.24 – Advantages and disadvantages of method W.....	51
Table E.25 – Advantages and disadvantages of method X.....	51
Table E.26 – Advantages and disadvantages of method Y.....	52
Bibliography.....	53

Foreword

This European Standard (EN 14255-2:2005) has been prepared by Technical Committee CEN/TC 169 "Light and lighting", the secretariat of which is held by DIN.

This European Standard shall be given the status of a national standard, either by publication of an identical text or by endorsement, at the latest by June 2006, and conflicting national standards shall be withdrawn at the latest by June 2006.

EN 14255 *Measurement and assessment of personal exposures to incoherent optical radiation* is published in four parts:

Part 1: Ultraviolet radiation emitted by artificial sources in the workplace.

Part 2 (this part): Visible and infrared radiation emitted by artificial sources in the workplace.

Part 3: UV-Radiation emitted by the sun (in preparation).

Part 4: Terminology and quantities used in UV-, visible and IR-exposure measurements.

According to the CEN/CENELEC Internal Regulations, the national standards organizations of the following countries are bound to implement this European Standard: Austria, Belgium, Cyprus, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Slovakia, Slovenia, Spain, Sweden, Switzerland and United Kingdom.

Introduction

People may be exposed to adversely high levels of visible (VIS) and/or infrared (IR) radiation in the workplace. The most important natural source for such VIS/IR-radiation is the sun. There are also artificial VIS/IR-radiation sources, where VIS- and/or IR-radiation is either intentionally emitted to achieve the purpose of the source's application or is unintentionally emitted.

Visible optical radiation (VIS-radiation): Common applications for sources intentionally emitting visible optical radiation are: general lighting, signalling devices, initiation of industrial-, medical- or agricultural-photochemical processes and phototherapy of patients (e.g. hyperbilirubinemia- and bright light therapy, physiotherapy and photodynamic therapy). Some examples of sources where visible radiation is unintentionally emitted are: welding arcs, industrial furnaces and some types of UV-sources. When people are irradiated by intense VIS-radiation, injuries may occur. VIS-radiation can cause damage to the retina through thermal or photochemical mechanisms. Photosensitization of the skin to visible light, usually due to the action of certain drugs, plants, or other substances, may occur shortly after administration of the drug (phototoxic sensitivity), or may occur only after a latent period which can vary from days to months (photoallergic sensitivity, or photoallergy). VIS-radiation may also induce or aggravate some diseases like porphyria.

Infrared optical radiation (IR-radiation): Common applications for sources intentionally emitting infrared optical radiation are: radiative heaters, military nightsight devices, phototherapy of patients (e.g. physiotherapy and photodynamic therapy), industrial photochemical or photothermal processes. Some examples of sources, where infrared radiation is unintentionally emitted, are: welding arcs, some types of visible light sources (e.g. high power tungsten lamps) and industrial furnaces. When people are irradiated by intense IR-radiation, injuries may occur. The anterior structures of the eyes (cornea) and the skin may be damaged by short term IR-irradiation of high irradiance. Depending on the wavelength a certain fraction of IR radiation can also cause damage to the retina through thermal or photochemical mechanisms. But additionally, long term less intense IR-irradiation may also result in cumulative damage to the eyes and skin, such as cataracts and skin aging.

In order to avoid short term injuries and reduce additional risks from long term overexposure to VIS- and/or IR-radiation, national regulations and international recommendations require restriction of VIS/IR-exposure levels in the workplace. To achieve this, it is necessary to determine the level of VIS/IR-exposure and assess its gravity.

The determination of the level of VIS/IR-exposure can be done by measurement of the VIS/IR-exposure of the people likely to be exposed. Determination of the severity of a VIS/IR-exposure is normally done by comparison of the determined exposure level with the required or recommended limit value. When the exposure level complies with the limit value no further action is necessary. When the limit value is exceeded protective measures have to be applied in order to decrease the VIS/IR-exposure. As the exposure situation at the workplace may change, it may be necessary to repeat the determination and assessment of VIS/IR-exposure at a later time.

VIS/IR radiation exposure measurements are often costly and time consuming. So it is reasonable to avoid measurements if possible, i. e. if the personal VIS/IR radiation exposure can be estimated and either exceeds the limit values by far or is far below the limit values. In some cases, the manufacturer may have classified a device according to European and International Standards such as EN 12198 and CIE S009. Knowledge of the classification of all potential sources of VIS/IR may allow a sufficiently precise assessment of hazard to be made without further measurement. Another approach could be to use known spectral data of sources in combination with calculation software in order to estimate exposure level [5]. VIS/IR-exposure measurements are only necessary if it cannot be estimated in advance whether the limit values will be exceeded or not. So as a first step of the assessment procedure it is useful to carry out a preliminary review including an exposure estimation.

This European Standard does not specify VIS/IR-exposure limit values. VIS/IR-exposure limit values are set in national regulations or provided by international organizations, such as the International Commission for Non-ionizing Radiation Protection (ICNIRP) [1]. This European Standard specifies the procedures for measurement and assessment of VIS/IR-exposures in the workplace. As the results of measurement and assessment of

EN 14255-2:2005 (E)

VIS/IR-exposure depend on the method of implementation, it is important to carry out measurements and assessments in a standardised way.

1 Scope

This European Standard specifies procedures for the measurement and assessment of personal exposures to visible (VIS) and infrared (IR) radiation emitted by artificial sources, where adverse effects cannot be readily excluded.

NOTE 1 Adverse effects will normally not occur in exposures caused by normal lighting or room heating.

This European Standard applies to VIS- and IR- exposures in indoor and outdoor workplaces. It does not apply to VIS- and IR-exposures in leisure time.

This European Standard does not apply to VIS- and IR- exposures caused by the sun.

NOTE 2 Part 3 of this standard will deal with UV-exposures caused by the sun.

This European Standard does not specify VIS- and IR-exposure limit values. It supports the application of limit values set by national regulations or international recommendations.

This European Standard applies to VIS- and IR- exposures by artificial incoherent sources, which emit spectral lines as well as continuous spectra. This European Standard does not apply to coherent radiation sources.

NOTE 3 Coherent optical radiation sources are covered by standards for lasers, like EN 60825-1 etc.

This European Standard applies to visible (VIS) and infrared (IR) radiation exposures in the wavelength band 380 nm to 3 μ m. It also applies to radiation exposures that may present a blue-light hazard in the wavelength band 300 nm to 700 nm.

This European Standard does not apply to other effects of which the action spectra lie solely within the UV-region 180 nm to 400 nm.

NOTE 4 Part 1 of EN 14255 addresses these effects.

This European Standard does not apply to radiation emissions of products.

NOTE 5 For radiation emissions of products other standards apply, such as EN 12198 for radiation emissions of machinery, EN 60335-2-27 for household appliances for skin exposures to ultraviolet and infrared radiation and CIE S009 for the safety of lamps and lamp systems.

This European Standard does not apply to heat stress, i.e. long term heating of the humans body with strain of the cardiac/circular system caused by climatic environmental conditions including VIS/IR radiation.

2 Normative references

The following referenced documents are indispensable for the application of this European Standard. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ENV 13005, *Guide to the expression of uncertainty in measurement*

EN 14255-1, *Measurement and assessment of incoherent optical radiation — Part 1: Ultraviolet radiation by artificial UV-sources in the workplace*

CIE 17.4:1987, *International electrotechnical vocabulary, Chapter 845: lighting*

3 Terms and definitions

3.1 Quantities, symbols and units

Table 1 – Quantities, symbols and units

Symbol	Quantity	Unit
λ	wavelength	nm
$E_{\lambda}(\lambda)$	spectral irradiance	W/(m ² ·nm)
E	irradiance	W/m ²
E_b	blue-light irradiance	W/m ²
$H_{\lambda}(\lambda)$	spectral radiant exposure	J/(m ² ·nm)
H	radiant exposure	J/m ²
H_b	blue-light radiant exposure	J/m ²
$L_{\lambda}(\lambda)$	spectral radiance	W/(m ² ·nm·sr)
L	radiance	W/(m ² ·sr)
L_r	retinal thermal radiance	W/(m ² ·sr)
L_b	blue-light radiance	W/(m ² ·sr)
G	radiance dose	J/(m ² ·sr)
G_b	blue-light radiance dose	J/(m ² ·sr)
Δt_{exp}	exposure duration	s
$b(\lambda)$	blue-light hazard weighting function	-
$r(\lambda)$	retinal thermal hazard weighting function	-
D	actual source diameter	m
D_L	viewing source diameter	m
r	viewing distance	m
α	angular subtense	mrad
ϕ	viewing angle	° / mrad
γ	angle of acceptance	mrad

NOTE Values for the spectral weighting function like $b(\lambda)$ and $b(\lambda)$ can be taken from the set of limit values applied. E.g. if $b(\lambda)$ is chosen to correspond to the ICNIRP relative spectral effectiveness $B(\lambda)$ [1,3], the blue-light irradiance E_b will correspond to the ICNIRP blue-light hazard weighted irradiance E_B and the blue-light radiant exposure H_b will correspond to the ICNIRP blue-light hazard weighted radiant exposure H_B (see 7.2).

3.2 Definitions and relationships between quantities

For the purposes of this European Standard, the terms and definitions given in CIE 17.4:1987 and the following apply.

3.2.1 irradiance

E

is calculated from the spectral irradiance $E_\lambda(\lambda)$ by:

$$E = \int_{\lambda_1}^{\lambda_2} E_\lambda(\lambda) d\lambda \quad (1)$$

3.2.2 blue-light irradiance

E_b

integral of the product of the spectral irradiance $E_\lambda(\lambda)$ and the blue-light hazard weighting function $b(\lambda)$:

$$E_b = \int_{\lambda_1}^{\lambda_2} E_\lambda(\lambda) b(\lambda) d\lambda \quad (2)$$

3.2.3 spectral radiant exposure

$H_\lambda(\lambda)$

integral of the spectral irradiance $E_\lambda(\lambda)$ with respect to the exposure duration Δt_{exp} :

$$H_\lambda(\lambda) = \int_{\Delta t_{\text{exp}}} E_\lambda(\lambda, t) dt \quad (3)$$

3.2.4 radiant exposure

H

integral of the irradiance E with respect to the exposure duration Δt_{exp} :

$$H = \int_{\Delta t_{\text{exp}}} E(t) dt \quad (4)$$

The radiant exposure H is calculated from the integral of the spectral radiant exposure $H_\lambda(\lambda)$:

$$H = \int_{\lambda_1}^{\lambda_2} H_\lambda(\lambda) d\lambda \quad (5)$$

3.2.5 blue-light radiant exposure

H_b

integral of the blue-light irradiance E_b with respect to the exposure duration Δt_{exp} :

$$H_b = \int_{\Delta t_{\text{exp}}} E_b dt \quad (6)$$

The blue-light radiant exposure H_b can also be calculated from the spectral radiant exposure $H_\lambda(\lambda)$ and the blue-light hazard weighting function $b(\lambda)$: